




QUICK START

LASER MEASURE
3 STEPS

- 1 SWITCH ON**
Short press . The laser dot comes on. It shuts off after 30 s idle – press to bring it back.
- 2 SET THE REFERENCE TO FRONT**
Long press until the display icon changes. Front is the laser end. Check it every time you switch on.



✗ BACK (DEFAULT)




✓ FRONT – USE THIS

- 3 MEASURE**
With the laser dot on, press . The reading shows on the bottom line in metres: **1.395 m = 1395 mm**.

⚠ Laser: never point at eyes.


MEASURE. IMPROVE. GO FASTER.



QUICK START

LASER MEASURE
3 STEPS

- 1 SWITCH ON**
Short press . The laser dot comes on. It shuts off after 30 s idle – press to bring it back.
- 2 SET THE REFERENCE TO FRONT**
Long press until the display icon changes. Front is the laser end. Check it every time you switch on.



✗ BACK (DEFAULT)




✓ FRONT – USE THIS

- 3 MEASURE**
With the laser dot on, press . The reading shows on the bottom line in metres: **1.395 m = 1395 mm**.

⚠ Laser: never point at eyes.


MEASURE. IMPROVE. GO FASTER.



QUICK START

LASER MEASURE
3 STEPS

- 1 SWITCH ON**
Short press . The laser dot comes on. It shuts off after 30 s idle – press to bring it back.
- 2 SET THE REFERENCE TO FRONT**
Long press until the display icon changes. Front is the laser end. Check it every time you switch on.



✗ BACK (DEFAULT)




✓ FRONT – USE THIS

- 3 MEASURE**
With the laser dot on, press . The reading shows on the bottom line in metres: **1.395 m = 1395 mm**.

⚠ Laser: never point at eyes.


MEASURE. IMPROVE. GO FASTER.




QUICK START

LASER MEASURE
3 STEPS

- 1 SWITCH ON**
Short press . The laser dot comes on. It shuts off after 30 s idle – press to bring it back.
- 2 SET THE REFERENCE TO FRONT**
Long press until the display icon changes. Front is the laser end. Check it every time you switch on.



✗ BACK (DEFAULT)



✓ FRONT – USE THIS

- 3 MEASURE**
With the laser dot on, press . The reading shows on the bottom line in metres: **1.395 m = 1395 mm**.

⚠ Laser: never point at eyes.

MEASURE. IMPROVE. GO FASTER.