




QUICK START


LASER MEASURE
3 STEPS

1 SWITCH ON


Short press . The laser dot comes on. It shuts off after 30 s idle – press  to bring it back.

2 SET THE REFERENCE TO **FRONT**

Long press  until the display icon changes. Front is the laser end. Check it every time you switch on.



✗ BACK (DEFAULT)



✓ FRONT – USE THIS

3 MEASURE

With the laser dot on, press . The reading shows on the bottom line in metres: **1.395 m = 1395 mm.**

 Laser: never point at eyes.

MEASURE. IMPROVE. GO FASTER.